

PHP - Technical Bulletin



Bulletin Number: TB-240201

Subject: P25AG One-Way Fuel Check Valve

Issue Date: Feb. 6, 2024


Scope: P25AG, 2kw Gas Heater

Complaint:

The original manual did not show the One-Way Check Valve required for the fuel system.

It is necessary to install this to ensure the fuel system will operate properly.

Failure to install this may cause starting problems and or inconsistent combustion.



Resolution:

Connect One-Way Check Valve in fuel system between fuel pump and heater as shown.

Arrow on Check Valve should be pointed in direction of fuel flow (towards heater).