

**Bulletin Number:** TB-240201

**Subject:** PH25AG-A and PH55AG-A One-Way Fuel Check Valve U65D-X419

**Issue Date:** Feb. 6, 2024 (Revised May 23, 2025)

**Scope:**

**Heater Kits:** [PH25AG-A](#) and [PH55AG-A](#)


**Heaters:** [P25A-T888](#) and [P55A-T888](#)

**Complaint:**

The original manual did not show the One-Way Check Valve required for the fuel system.

It is necessary to install this to ensure the fuel system will operate properly.

Failure to install this may cause starting problems and or inconsistent combustion.



**Resolution:**

Connect One-Way Check Valve U65D-X419 in fuel system between fuel pump and heater as shown.

Arrow on Check Valve should be pointed in direction of fuel flow (towards heater).